National Transportation Safety Board Washington, DC 20594

Brief of Accident

Adopted 09/11/1992

CHI	90	MΑ	۱24	44

Airplane

File No. 2123	08/27/1990	ELKHORN, WI	Aircraft Reg No.	N16933	Tir	me (Local): 01:00 CDT
Engine Make Aircraft Di Number of E Operating Certifi Name of Type of Flight Op	/Model: BELL / 206B /Model: ALLISON / 250-C20B amage: Destroyed ngines: 1 cate(s): On-demand Air Taxi Carrier: OMNIFLIGHT HELICO eration: Non-scheduled; Dome: Under: Part 135: Air Taxi & Co	stic; Passenger Only	Crew Pass	Fatal 1 4	Serious 0 0	Minor/None 0 0
Last Depart Dest	. Point: Same as Accident/Incidination: CHICAGO , IL oximity: Off Airport/Airstrip			Weathe Basic Lowe Wind Temper	Visibility: .0 Dir/Speed: ature (°C): U	Vitness) Ft. AGL, Unknown 00 SM
Pilot-in-Command	Age: 42			Flight Ti	me (Hours)	
Certificate(s)/Rating(s) Flight Instructor; Commercial; Single-engine Land; Helicopter nstrument Ratings				Las	All Aircraft: 5 st 90 Days: 2 ake/Model: 1	264

FOUR HELICOPTERS WERE BEING USED AT NIGHT TO TRANSPORT A CONCERT GROUP FROM A GOLF COURSE AREA NEAR ELKHORN, WI, TO CHICAGO, IL. AS THE THIRD HELICOPTER (N16933) WAS DEPARTING, IT REMAINED AT A LOWER ALTITUDE THAN THE OTHERS, AND THE PILOT TURNED SOUTHEASTERLY TOWARD RISING TERRAIN. SUBSEQUENTLY, THE HELICOPTER CRASHED ON HILLY TERRAIN ABOUT 3/5 MI FROM THE TAKEOFF POINT. ELEVATION OF THE CRASH SITE WAS ABOUT 100 FT ABOVE THE GOLF COURSE AND 50 FT BELOW THE SUMMIT OF THE HILL. NO PREIMPACT PART FAILURE OR MALFUNCTION WAS FOUND DURING THE INVESTIGATION. PILOTS OF THE OTHER HELICOPTERS REPORTED VFR FLIGHT CONDITIONS WITH SOME FOG. A GROUND WITNESS NEAR THE CRASH SITE REPORTED HAZE AND GROUND FOG OF VARYING INTENSITY WITH PATCHES OF LOW CLOUDS, BUT SAID STARS COULD BE SEEN THROUGH THE FOG.

Total Instrument Time: 132

Brief of Accident (Continued)

CHI90MA244

File No. 2123 08/27/1990 ELKHORN, WI Aircraft Reg No. N16933 Time (Local): 01:00 CDT

Occurrence #1: IN FLIGHT COLLISION WITH TERRAIN/WATER

Phase of Operation: TAKEOFF - INITIAL CLIMB

Findings

- 1. (C) PLANNING/DECISION IMPROPER PILOT IN COMMAND
- 2. (F) LIGHT CONDITION DARK NIGHT
- 3. (F) WEATHER CONDITION FOG
- 4. (F) WEATHER CONDITION HAZE/SMOKE
- 5. (F) TERRAIN CONDITION RISING
- 6. (C) PROPER ALTITUDE NOT ATTAINED PILOT IN COMMAND
- 7. (F) VISUAL/AURAL PERCEPTION PILOT IN COMMAND

Findings Legend: (C) = Cause, (F) = Factor

The National Transportation Safety Board determines the probable cause(s) of this accident as follows.

IMPROPER PLANNING/DECISION BY THE PILOT, AND HIS FAILURE TO ATTAIN ADEQUATE ALTITUDE BEFORE FLYING OVER RISING TERRAIN AT NIGHT. FACTORS RELATED TO THE ACCIDENT WERE: DARKNESS, FOG, HAZE, RISING TERRAIN, AND THE LACK OF VISUAL CUES THAT WERE AVAILABLE TO THE PILOT.